



Western Michigan University
ScholarWorks at WMU

Legacy Scout Tickets from Pure Oil Company

8-20-2021

MGRRE_PureOilScoutTickets_Goble, Warren_2_21159062790000

MGRRE

Western Michigan University

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

WMU ScholarWorks Citation

MGRRE, "MGRRE_PureOilScoutTickets_Goble, Warren_2_21159062790000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 10071.

<https://scholarworks.wmich.edu/pure/10071>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



MGRRE_PureOilScoutTickets_Goble, Warren_2_21159062790000

API 21159062790000

Permit Number 6279

Lease Name Goble, Warren

Well Number 2

County Van Buren

Township 01S

Range 14W

Section 13

2021 DEQ or Pure co_name Shoemaker, William P.

Pure Number 455

Latitude 42.3761

Longitude -85.88441

THE PURE OIL COMPANY

DATE June 8, 1939

LOCATION REPORT

No. 455

STATE Mich. COUNTY Van Buren DIST. Bloomingtondale TWP. Bloomingtondale SEC. 13 TOWN 1-5 RANGE 14 W

WELL No. 2 (SERIAL No. 455) FARM W. Goble ACRES

NAME OF STREAM OR WATERS QUADRANGLE SE SW SE

OPERATOR W. P. Shoemaker Map Bloomingtondale Township, Van Buren County
W. P. Shoemaker Bloomingtondale - Van Buren.

Feet from North Line of Farm

	"	"	East	"	"	"
<u>250</u>	"	"	South	"	"	"
<u>990</u>	"	"	West	"	"	"

Feet from North Line of Section


	"	"	East	"	"	"
<u>250</u>	"	"	South	"	"	"
<u>990</u>	"	"	West	"	<u>1/4</u>	"

Loc

LEGEND

- | | |
|------------------|----------------------|
| ○ LOCATION | ⊙ DRY HOLE |
| ⊙ RIG | ⊙ DRY SHOWING OIL |
| ⊕ DRILLING | ⊙ DRY SHOWING GAS |
| ☀ GAS WELL | ⊙ ABANDONED LOCATION |
| ● OIL WELL | ☀ ABANDONED GAS WELL |
| ⬮ SMALL OIL WELL | ⬮ ABANDONED OIL WELL |

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

R. L. Yeager

Superintendent or Foreman.

